







Kitchavent – Grease, Smoke and Odour Control

Kitchavent System Maintenance Guidelines					
	Kitchavent 2000 Light Grease and Odour Control	Kitchavent 3000 Heavy Grease and Odour Control	Kitchavent 4000 Heavy Grease, Smoke and Odour Control	Notes	Approximate Replacement Costs
Mesh Grease Filters 		Washable Weekly	Washable Weekly	Replacement will be required approx 1-2 years.	£35 per Filter
F5 GP Bag Filters 	Replace 3 Monthly	Replace 3 Monthly	Replace 3 Monthly		£25 / Filter
HEPA Filters 			Replace 1-3 Monthly	Spares are recommended to be kept on site.	£200 / Filter
Activated Carbon 	Replace 6-12 Monthly	Replace 6-12 Monthly	Replace 6-12 Monthly		£330 / Filter

Please Note: Maintenance requirements for the Kitchavent System can vary depending on the style of cooking and number of covers.